

Additional Materials


East Harwich Methodist Cemetery
Gravestone Conservation and Preservation

Pictures of damaged gravestones and map
with their location

EAST HARWICH METHODIST CEMETERY






2008 MAP

UNION CEMETERY








^m (48) THESE ARE DIRECT DESCENDANTS OF THE MAYFLOWERS





Section A

Grave	Lot	Date of Death	Photo
A2	Mehitable Cahoon In 2 pieces and down on face	1862	
A3	Seth Cahoon In 2 pieces and down on face	1875	
A17	Sylvanus Eldredge & his wife Elisaha B Eldredge In 2 piece and down on back	1831 1840	
A22	Stone at least 2 pieces ad down of face unreadable		
A24	Emma Cahoon (dau of Ezekiel & Polly) Crack starting at base running up to midway of stone	4 May 1866	



Section A

			
A32	Orick Elwyn Doane 2 pieces maybe more buried down on back	1850	
A36	Benjamin Young Jr. in 4 pieces	1861	
A39	Benjamin Young down on back	1874	
A59	Betsey S Eldridge at least 2 pieces down of face	1860	





Section A

A60	<p>Clarinton Eldridge</p> <p>3 pieces</p>	1879	
A61	<p>Vinson Cahoon</p> <p>2 pieces face down new Fresh brake.</p>	1876	
A62	<p>Cynthia Cahoon</p> <p>2 pieces</p>	1877	
A	<p>Clifford lot</p> <p>Corner markers need to be reset</p>	1902-1927	



Section B & C

Grave	Lot	Date of Death	Photo
B2	<p>Maria K Nickerson</p> <p>Crack previous repair will need to be stabilized and conserved</p>	1837	
B11	<p>Woodbury Norcross Gardner Nickerson</p> <p>Monument is leaning and has crack at base pins will have to be removed and memorial reset</p>	4 Mar 1859	





Section B & C

B14	Elnathan Nickerson at least 3 pieces buried back side down	1861	
C8	<p>Patience Howes Crowell</p> <p>at least 3 pieces previous repair starting to fail</p>	1881	 
C16	<p>Marion M dau of Nathan & Polly Robbins</p> <p>Additional name at bottom of stone but buried under ground, previous repair at least 3 pieces.</p>	<p>1865 (21y 5m 8d)</p> <p>1865 (2y 3m 6d)</p>	



Section D & E

Grave	Lot	Date of Death	Photo
D1	Emma N Cahoon 2 pieces medal pins will need to be removed and memorial to be reset	1876	
E2	Rebecca Small Slate memorial to be conserved and foot stone to be reset	1852	







Section F

Grave	Lot	Date of Death	Photo
F4	<p>Rachel Linnell</p> <p>Brown stone flaking off needs to be consolidated and conserved</p>	<p>1826</p> <p>Died 29 Aug 1826 in Harwich Rachel Wixon Wife of Uriah Linnell</p>	
F12	<p>Captain James Taylor</p> <p>At least 2 pieces stone is buried face up</p>	1854	
F17	<p>Erastus O Cahoon</p> <p>Unsure if any pieces are broken face up edges buried</p>	1852	
F25	<p>Thankful Young</p> <p>Slate memorial delaminating</p>	1842	






Section F

			
F31	Polly Robbins Wife of Capt Nathan Face down	19 Aug 1886	



Section G

Grave	Lot	Date of Death	Photo
G5	Seth Cahoon Crack down the center of the stone starting at the top	1857	
G8	Anna wife of Jesse L Eldredge Stone down on back	1882	
G18	Ursilla E Kelley Previously repaired crack stone in at least 2 pieces	1854	
G19	Allen Kenney Stone broken off at base and previously repaired crack. Total 3 pieces		
G20	Priscilla Kenney Previously repaired Stone 4 pieces	1850	
G23	Joshua Nickerson Stone cracked face up not sure if more piece's chips are breaking off at top of memorial	1827	




Section G

<p>G25</p>	<p>Captain Edward Nickerson</p> <p>8 Nov 1820</p> <p>Extremely hard to read missing piece hopefully buried in the ground and can be restored.</p> <p>Brownstone broken in half and footstone cracked down center</p>	<p>8 Nov 1820</p>	
<p>G28</p>	<p>Sally Kenney</p> <p>At least 3 pieces visible down on back face up</p>	<p>1866</p>	
<p>G41</p>	<p>Sarah Nickerson</p> <p>Previous repair using bolts in at least 3 pieces.</p>	<p>1857</p>	
<p>G42</p>	<p>Tulley Nickerson</p> <p>Broken in at least 2 pieces</p>	<p>1854</p>	
<p>G45</p>	<p>Cyrena Eldredge</p> <p>Previous repair broken off at base 3 pieces</p>	<p>1826</p>	




Section G

<p>G49</p>	<p>Enos and John Rogers</p> <p>Previous repair cracked reopening</p>	<p>Enos Rogers 14 Dec 1857 Son John Rogers Lost at sea 7 Dec 1825</p>	
<p>G50</p>	<p>Molly Rogers</p> <p>Down on back face up</p>	<p>1861</p>	

Section H

Grave	Lot	Date of Death	Photo
H7	<p>Bathsheba Young</p> <p>Brown stone crack previous repair. Flaking off on face of stone needs to be conserved</p>	1827	
H8	<p>Captain Samuel Doane</p> <p>2 pieces down on back face up</p>	1827	
H9	<p>Sallie Doane</p> <p>Cracked across the center of stone</p>	1868	

Section H

<p>H10</p>	<p>Reuben Eldredge</p> <p>Flaking off of layers delaminating face of stone must be conserved to prevent future damage</p>	<p>1824</p>	
<p>H11</p>	<p>Sarah Eldredge</p> <p>Flaking off of layers delaminating face of stone must be conserved to prevent future damage</p>	<p>1826</p>	
<p>H12 A & B</p>	<p>Samuel Ellis Hannah Ellis</p> <p>At least 2 pieces broken and buried back side down</p>	<p>1853 1887</p>	
<p>H16</p>	<p>Captain Elry Small</p> <p>At least 4 pieces down on back face up</p>	<p>January 14 1853 Age 49 years 9 months</p>	